

7th October, 1976

Mr. S.G. Fraser,
14 Nagle Road,
SALISBURY EAST, S.A. 5109

Reply in Negative sent 13/10/76

Dear Mr. Fraser,

ROTRON MARK 4 FAN MODIFICATION

It is necessary due to a potential hazard to modify all Rotron Mark 4 fans which may be fitted to your DEC computer equipment.

Please will you check all the fans in each piece of DEC equipment to see if you have any of these fans - see picture. A quick check is to look for three bladed fans and then look for the MK4 inscription.

Should you require an engineer to check your equipment, I can arrange this for you at per call rates of \$27 per hour.

The modification must be installed by a DEC Field Service engineer. The charge will be \$27 per hour, with a \$27 minimum charge and parts will be supplied by DEC without charge.

Will you return the attached form to me as soon as possible, so that I can arrange for an engineer to call?

If I can be of any further assistance, please do not hesitate to contact me.

Yours faithfully,


H John Ball

J. Ball
FIELD SUPPORT ENGINEER

JB/srw

Enc.

SYDNEY (Head Office)	123 WILLOUGHBY RD., CROWS NEST, N.S.W.	2065	..	TELEPHONE 439 2566	..	TELEX 20740
MELBOURNE	60 PARK ST., SOUTH MELBOURNE, VIC.	3205	..	TELEPHONE 699 2888	..	TELEX 30700
PERTH	643 MURRAY ST., WEST PERTH, W.A.	6005	..	TELEPHONE 21 4993	..	TELEX 92140
BRISBANE	133 LEICHHARDT ST., STH. BRISBANE, QLD	4101	..	TELEPHONE 29 3088	..	TELEX 40616
ADELAIDE	6 MONTROSE AVE., NORWOOD, S.AUST.	5067	..	TELEPHONE 42 1339	..	TELEX 82825
CANBERRA	24 KEMBLA ST., FYSHWICK, A.C.T.	2609	..	TELEPHONE 95 3588	..	TELEX 62621
HOBART	SUITE 205, 86 MURRAY ST., HOBART, TAS.	7000	..	TELEPHONE 23 5114	..	TELEX 58215



The rear surface of this Rotron Mark 4 fan was painted white to permit a photographic presentation of the raised lettering.